OMB Control No.: 2127-0004

90

Part 573 Safety Recall Report

19V-332

🔂 🔆 🗥 🕁

Number of potentially involved :

Estimated percentage with defect : 5 %

Population :

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Manufacturer Name :PRIME-TIME SPECIALTY VEHICLESSubmission Date :MAR 01, 2019NHTSA Recall No. :19V-332Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : PRIME-TIME SPECIALTY VEHICLES Address : 56616 ELK PARK DRIVE ELKHART IN 46516 Company phone : 574-293-9191

Vehicle Information :

Vehicle 1:	2016-2018 Ram ProMaster		
Vehicle Type :	LIGHT VEHICLES		
Body Style :	VAN		
Power Train :			
Descriptive Information :	Several vehicles were affected by the recall. Most however were not found to have faulty equipment that was recalled.		
	Once the recall notice was presented to Prime Time Specialty Vehicles, corporate management audited all potential VINS that may have been affected from the notice.		
	All VINS that were found to have the potential recall were distributed to the selling dealer and/or end user. Once the dealer/end user was contacted, a through test was made by a local automotive dealer. The testing that was done to these vehicles was provided from Freedman Seating.		
	All vehicles that had recalled equipment were immediately taken out of service, and repairs parts, manuals, and servicing assistance were provided by Freedman Seating.		
Production Dates :	JAN 01, 2016 - JUL 31, 2018		
VIN Range 1:	Begin :NREnd :NRNot sequential		
	Several vehicles were affected by the recall. Most however were not found to have faulty equipment that was recalled.		
	Once the recall notice was presented to Prime Time Specialty Vehicles, corporate management audited all potential VINS that may have been affected from the notice.		
The information contained in this report was submitted pursuant to 49 CFR §573			

Part 573 Safety Recall Report

19V-332

Page 2

All VINS that were found to have the potential recall were distributed to the selling dealer and/or end user. Once the dealer/end user was contacted, a through test was made by a local automotive dealer. The testing that was done to these vehicles was provided from Freedman Seating.

All vehicles that had recalled equipment were immediately taken out of service, and repairs parts, manuals, and servicing assistance were provided by Freedman Seating.

Production Dates : JAN 04, 2016 - JUL 01, 2018

VIN Range 1 : Begin :	1FBVU4XM2HKB04732	End :	1FBVU4XM8HKB04735	Not sequential
VIN Range 2 : Begin :	1FBVU4XM2HKB04732	End :	1FBVU4XM8HKB04735	Not sequential
VIN Range 3 : Begin :	1FBVU4XM3HKB08479	End :	1FBVU4XM1HKB08481	Not sequential
VIN Range 4 : Begin :	1FBVU4XM2HKB04732	End :	1FBVU4XM8HKB04735	Not sequential
VIN Range 5 : Begin :	1FBVU4XM3HKB08479	End :	1FBVU4XM1HKB08481	Not sequential
VIN Range 6 : Begin :	1FBVU4XM3HKB08479	End :	1FBVU4XM1HKB08481	Not sequential
VIN Range 7 : Begin :	1FDZX2CM0GKA21372	End :	1FDZX2CM0GKA21376	Not sequential
VIN Range 8 : Begin :	1FTNR2XM5FKB12967	End :	1FTNR2XM5FKB12977	Not sequential
VIN Range 9 : Begin :	1FTNR2XM5FKB12967	End :	1FTNR2XM5FKB12977	Not sequential
VIN Range 10 : Begin :	1FTNR2XM5FKB12967	End :	1FTNR2XM5FKB12977	Not sequential
VIN Range 11 : Begin :	1FDZX2CM0GKA21373	End :	1FDZX2CM0GKA21376	□ Not sequential

Description of Defect :

Description of the Defect :	Freedman Seating Company (FSC) has determined that our GO-ES Foldaway Seat may have a defect which may increase the risk in occupant injury in the event of a vehicle collision. These seats may have been manufactured with a back frame weldment that is too narrow resulting in deformation of the seat back cushion dump mechanism which may cause it to malfunction.
FMVSS 1 :	207 - Seating systems
FMVSS 2 :	210 - Seat belt assembly anchorages
Description of the Safety Risk :	If this mechanism does malfunction the seat back cushion may not support the appropriate loading in the event of a front or rear vehicle collision.
Description of the Cause :	During the operation of the seat and, specifically, in rotating the seat back cushion from the stowed to the upright, design use position there needs to be an audible click of the mechanism locking into position. In addition, the mechanism handle will rotate downwards. There may be some seats where the mechanism does not fully engage during this operation of the seat back cushion.
Identification of Any Warning that can Occur :	Index Pin inspection. Is pin bent? No = Pass Yes = Fault

Supplier Identification :

Component Manufacturer

Name : Freedman Seating Company Address : 4545 West Augusta BLVD

Chicago ILLINOIS 60651

Country: United States

Chronology:

Check shipping date under seat. Seats shipped July 2018 and after do not need any repair. Index Pin inspection. Is pin bent? No = Pass Pin is located opposite of recliner handle as shown below.

Seatback lock inspection. All checks must pass for the seat to be considered locked.

A. Rotate seatback to in-use position. Does it take significant effort to rotate? No = Pass

B. Set seatback between the in-use and stowed positions and release handle. Slowly move seatback to in-use position.

1. Does recliner make an audible click noise indicating it is locked? Yes = Pass

2. Does recliner handle rotate all the way down in one motion? Yes = Pass

C. Apply forward and backward pressure to seatback. Does seatback remain locked? Yes = Pass D. Set seatback to in-use position. See video.

1. While applying forward pressure to back of the seat, lift release handle just enough to disengage seatback. Do not manually lift handle all the way. The position of disengagement is somewhere between the handle's locked and fully unlocked position.

2. Release handle and move seatback back and forth near the in-use position.

i. Does it sound/feel like the mechanism is ratcheting? No = Pass

ii. Does it take significant effort to rotate seatback? No = Pass

Description of Remedy :

Description of Remedy Program :	To correct this condition, FSC will facilitate the inspection and any necessary repairs. An Inspection & Service Procedure is attached that provides instruction on how to inspect the seat and repair it if necessary. These documents can also be found here: https://www.freedmanseating.com/instructions/go-es-foldaway
	After seat inspection and a determination the seat is defective the customer shall complete the Recall Order Repair Form which can be downloaded at https://www.freedmanseating.com/instructions/go-es-foldaway and email FSC Customer to order a Recall Parts Kit. To ensure the email is not mistakenly identified as spam the email subject line must include: GO-ES Foldaway Seat Recall. No repair parts will be sent unless the form is completely filled out.
	The expected time to complete the seat repair is 30 minutes per seat. FSC will reimburse the cost of repairs related to this recall including parts and labor. The reimbursement will be \$50.00/seat. Upon completion of the recall repair work the Customer must file a claim with FSC Customer Service for reimbursement referencing FSC Recall #18E-076 on the claim.
	FSC Recall Contact: Terry Gogins or Anthony Lee or Anna Kurzawa Customer Service Representative Freedman Seating Company 4545 W Augusta Blvd Chicago, IL 60465 800-443-4540 Terry.gogins@freedmanseating.com Anthony.lee@freedmanseating.com
· -	Index Pin inspection. Is pin bent? No = Pass Pin is located opposite of recliner handle as shown below.
	 A. Rotate seatback to in-use position. Does it take significant effort to rotate? No = Pass B. Set seatback between the in-use and stowed positions and release handle. Slowly move seatback to in-use position. 1. Does recliner make an audible click noise indicating it is locked? Yes = Pass 2. Does recliner handle rotate all the way down in one motion? Yes = Pass C. Apply forward and backward pressure to seatback. Does seatback remain locked? Yes = Pass D. Set seatback to in-use position. See video. While applying forward pressure to back of the seat, lift release handle just enough

Part 573 Safety Recall Report

Identify How/When Recall Condition was Corrected in Production :	to disengage seatback. Do not manually lift handle all the way. The position of disengagement is somewhere between the handle's locked and fully unlocked position. 2. Release handle and move seatback back and forth near the in-use position. i. Does it sound/feel like the mechanism is ratcheting? No = Pass ii. Does it take significant effort to rotate seatback? No = Pass If all inspections pass, seat does not need any repair. If any of the inspections fail, perform repair per detailed instructions using service kit (FSC Part Number: 44200). Prime-Time Specialty Vehicles corrected the issue after all vehicles had left our facility. Several vehicles were affected by the recall. Most however were not found to have faulty equipment that was recalled. Once the recall notice was presented to Prime Time Specialty Vehicles, corporate management audited all potential VINS that may have been affected from the notice. All VINS that were found to have the potential recall were distributed to the selling dealer and/or end user. Once the dealer/end user was contacted, a through test was made by a local automotive dealer. The testing that was done to these vehicles was provided from Freedman Seating. All vehicles that had recalled equipment were immediately taken out of service, and repairs parts, manuals, and servicing assistance were provided by Freedman Seating.
Recall Schedule : Description of Recall Schedule :	Once the recall notice was presented to Prime Time Specialty Vehicles, corporate management audited all potential VINS that may have been affected from the notice.

All VINS that were found to have the potential recall were distributed to the selling dealer and/or end user. Once the dealer/end user was contacted, a through test was made by a local automotive dealer. The testing that was done to these vehicles was provided from Freedman Seating.

Notices were provided through phone call, email, and US Mail Postage.

Part 573 Safety Recall Report

19V-332

Planned Dealer Notification Date :FEB 28, 2019 - APR 30, 2019Planned Owner Notification Date :FEB 28, 2019 - APR 30, 2019

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573