94

# Part 573 Safety Recall Report

Manufacturer Name :EHG USA LP dba American FastbacksSubmission Date :APR 23, 2019NHTSA Recall No. :19V-320Manufacturer Recall No. :NR



Number of potentially involved :

Estimated percentage with defect : 60 %

19V-320

#### Manufacturer Information :

Manufacturer Name : EHG USA LP dba American Fastbacks Address : 1945 Burgundy Place Ontario CA 91761 Company phone : 390-0002

**Vehicle Alterer Information :** 

# Vehicle 1 :2018-2018 Jeep WranglerDescriptive Information :Presently, American Fastbacks Edition Badlands model Jeep Wrangler vehicles<br/>with an installed roof top tent are a possible safety risk. A Chinese part supplier<br/>quality issue is causing the roof top tent to crack under extreme weather<br/>conditions which can lead to the top cover becoming detached from a driving<br/>vehicle.Production Dates :JAN 08, 2018 - DEC 21, 2018

**Population**:

### **Description of Defect :**

Description of the Defect :	EHG USA LP d/b/a American Fastbacks ("Company") is a second-stage OEM and/or alterer of Jeep Wranglers purchased directly from Fiat Chrysler Automobiles ("FCA") group. During the upfitting stage, the Company shop employees install a roof top tent and brackets to the Badlands model vehicles. This roof top tent was purchased directly from a Chinese manufacturer who ensured all quality requirements such as fit, form and function were met. The Company has learned that the roof top tents fail (e.g. large cracks on top cover) under extreme weather conditions (cold).
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	A broken or crack top cover can become detached from the tent assembly if sufficient wind is caught underneath it when the vehicle is in motion. The suspect vehicles were shipped to customers with a tie down strap for prevention of any disengaged part of the roof top tent. The population of affected vehicles is the same as the ones listed in NHTSA ID: 19V190.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	None

The information contained in this report was submitted pursuant to 49 CFR §573

## **Part 573 Safety Recall Report**

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : NR Address : NR NR Country : NR

#### **Chronology**:

NR

#### **Description of Remedy :**

Description of Remedy Program :	NR
How Remedy Component Differs from Recalled Component :	NR
Identify How/When Recall Condition was Corrected in Production :	NR

#### **Recall Schedule :**

Description of Recall Schedule :	NR	
Planned Dealer Notification Date :	NR	- NR
Planned Owner Notification Date :	NR	- NR

#### **Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : Address :

Country : Company Phone :

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573

**19V-320**