## **Recall Quarterly Report**

20V-374

Manufacturer Name : Chrysler (FCA US, LLC) NHTSA Recall No. / MFR Recall No. : 20V-374 /W52 Recall Subject : Side Curtain Air Bag May Not Properly Inflate Owner Notification Beginning Date : JUL 16, 2020 Owner Notification End Date: JUL 16, 2020



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	JAN 19, 2021	2020-4	114	55	2	0
1	OCT 21, 2020	2020-3	114	40	0	0

This Document Last Updated : JAN 19, 2021

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.

The information contained in this report was submitted pursuant to 49 CFR §573.7