The information contained in this report was submitted pursuant to 49 CFR §573

OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :Chrysler (FCA US LLC)Submission Date :AUG 27, 2020NHTSA Recall No. :20E-060Manufacturer Recall No. :W64

Manufacturer Information :

Manufacturer Name : Chrysler (FCA US LLC) Address : 800 Chrysler Drive CIMS 482-00-91 Auburn Hills MI 48326-2757 Company phone : 1-800-853-1403

Equipment Information :

| Brand / Trade 1: | Mopar |
|---------------------------|---|
| Model : | Crew - Big Horn/Laramie All-Weather Floor Mat Kit 1N8 color |
| Part No. : | 82215320AB |
| Size : | NR |
| Function : | NR |
| Descriptive Information : | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. The scope was determined by sales records of the suspect parts. Similar floor mats not included in the recall were manufactured with a different design. The total affected parts for this part number is 2,641. |
| Production Dates : | NOV 01, 2017 - FEB 01, 2020 |
| | |



Number of potentially involved : 34,034 Estimated percentage with defect : 1 %

Population :

20E-060

| Brand / Trade 2 : | |
|---------------------------|---|
| Model : | 6 |
| | 82215320AC |
| Size : Function : | |
| | |
| Descriptive information : | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. |
| | The scope was determined by sales records of the suspect parts. |
| | Similar floor mats not included in the recall were manufactured with a different design. |
| | The total affected parts for this part number is 359. |
| Production Dates : | NOV 01, 2017 - FEB 01, 2020 |
| Brand / Trade 3: | Monar |
| | Crew - Big Horn/Laramie All-Weather Floor Mat Kit 1X7 color |
| | 82215321AB |
| Size : | |
| Function : | |
| | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. |
| | The scope was determined by sales records of the suspect parts. |
| | Similar floor mats not included in the recall were manufactured with a different design. |
| | The total affected parts for this part number is 5,176. |
| Production Dates : | NOV 01, 2017 - FEB 01, 2020 |

| | Mopar Crew - Big Horn/Laramie All-Weather Floor Mat Kit 1X7 color 82215321AC |
|---------------------------|---|
| Size : | NR |
| Function : | NR |
| Descriptive Information : | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. |
| | The scope was determined by sales records of the suspect parts. |
| | Similar floor mats not included in the recall were manufactured with a different design. |
| | The total affected parts for this part number is 18,831. |
| Production Dates : | NOV 01, 2017 - FEB 01, 2020 |
| Brand / Trade 5 : | Monar |
| | Quad - Big Horn/Laramine All-Weather Floor Mat Kit 1N8 Color |
| | 82215322AB |
| Size : | NR |
| Function : | NR |
| Descriptive Information : | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. |
| | The scope was determined by sales records of the suspect parts. |
| | Similar floor mats not included in the recall were manufactured with a different design. |
| | The total affected parts for this part number is 1,304. |
| Production Dates : | NOV 01, 2017 - FEB 01, 2020 |

| Brand / Trade 6: | Mopar |
|---------------------------|---|
| | Quad - Big Horn/Laramine All-Weather Floor Mat Kit 1X7 Color |
| | 82215323AB |
| Size : | |
| Function : | NR |
| Descriptive Information : | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. |
| | The scope was determined by sales records of the suspect parts. |
| | Similar floor mats not included in the recall were manufactured with a different design. |
| | The total affected parts for this part number is 2,459. |
| Production Dates : | NOV 01, 2017 - FEB 01, 2020 |
| | |
| Brand / Trade 7 : | - |
| | Quad - Big Horn/Laramine All-Weather Floor Mat Kit 1N8 Color 82215322AC |
| Size : | |
| Function : | |
| | |
| bescriptive mormation. | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. |
| | The scope was determined by sales records of the suspect parts. |
| | Similar floor mats not included in the recall were manufactured with a different design. |
| | The total affected parts for this part number is 191. |
| Production Dates : | NOV 01, 2017 - FEB 01, 2020 |

| Brand / Trade 8: | • |
|---------------------------|---|
| | Quad - Big Horn/Laramine All-Weather Floor Mat Kit 1X7 Color |
| | 82215323AC |
| Size : | |
| Function : | |
| Descriptive Information : | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. |
| | The scope was determined by sales records of the suspect parts. |
| | Similar floor mats not included in the recall were manufactured with a different design. |
| | The total affected parts for this part number is 2,424. |
| Production Dates : | NOV 01, 2017 - FEB 01, 2020 |
| | |
| Brand / Trade 9: | • |
| | Quad - Rebel All-Weather Floor Mat Kit 1XR Color |
| | 82215421AB |
| Size : Function : | |
| | |
| Descriptive information : | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. |
| | The scope was determined by sales records of the suspect parts. |
| | Similar floor mats not included in the recall were manufactured with a different design. |
| | The total affected parts for this part number is 149. |
| Production Dates : | NOV 01, 2017 - FEB 01, 2020 |
| | |

| Brand / Trade 10: | Mopar |
|---------------------------|---|
| Model : | Quad - Rebel All-Weather Floor Mat Kit 1XR Color |
| Part No. : | 82215421AC |
| Size : | NR |
| Function : | NR |
| Descriptive Information : | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. |
| | The scope was determined by sales records of the suspect parts. |
| | Similar floor mats not included in the recall were manufactured with a different design. |
| | The total affected parts for this part number is 1. |
| Production Dates : | NOV 01, 2017 - FEB 01, 2020 |
| Brand / Trade 11 : | Mopar |
| Model : | Crew - Rebel All-Weather Floor Mat Kit 1XR Color |
| Part No. : | 82215422AB |
| Size : | NR |
| Function : | NR |
| Descriptive Information : | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. |
| | The scope was determined by sales records of the suspect parts. |
| | Similar floor mats not included in the recall were manufactured with a different design. |
| | The total affected parts for this part number is 196. |
| Production Dates · | NOV 01, 2017 - FEB 01, 2020 |

| Brand / Trade 12: | Mopar |
|---|--|
| | Crew - Rebel All-Weather Floor Mat Kit 1XR Color |
| Part No. : | 82215422AC |
| Size : | NR |
| Function : | NR |
| Descriptive Information : | Some Mopar all-weather floor mat kits sold in calendar year 2018, 2019 and 2020 may allow interference between the driver all-weather floor mat and the accelerator pedal on 2019-2020 Model Year Ram 1500 vehicles with adjustable pedals. |
| | The scope was determined by sales records of the suspect parts. |
| | Similar floor mats not included in the recall were manufactured with a different design. |
| | The total affected parts for this part number is 303. |
| Production Dates : | NOV 01, 2017 - FEB 01, 2020 |
| | |
| Description of Defect : Description of the Defect | : The accelerator pedal may, in certain circumstances, interfere with the raised feature on an all-weather floor mat, possibly inhibiting the accelerator pedal from promptly repositioning to a lesser depressed position after the driver releases pressure on the accelerator pedal. |
| FMVSS 1 | • • |
| FMVSS 2 | |
| | : If the accelerator pedal interferes with the mat, the vehicle may not decelerate as expected when the driver releases the accelerator pedal, which can cause a vehicle crash without prior warning. By continued braking, however, the driver can activate brake-throttle override to close the throttle and bring the vehicle to a safe stop. |
| Description of the Cause | |
| Identification of Any Warnin | |

Identification of Any Warning None that can Occur :

Involved Components :

20E-060

Page 8

| Component Name : | Mopar All-Weather Floor Mat Kit | |
|-------------------------|---------------------------------|--|
| Component Description : | Mopar All-Weather Floor Mat Kit | |
| Component Part Number : | 82215320AB | |
| Component Name : | Mopar All-Weather Floor Mat Kit | |
| Component Description : | Mopar All-Weather Floor Mat Kit | |
| Component Part Number : | 82215320AC | |
| Component Name : | Mopar All-Weather Floor Mat Kit | |
| - | Mopar All-Weather Floor Mat Kit | |
| Component Part Number : | 82215321AB | |
| Component Name : | Mopar All-Weather Floor Mat Kit | |
| • | Mopar All-Weather Floor Mat Kit | |
| Component Part Number : | - | |
| Component Name : | Mopar All-Weather Floor Mat Kit | |
| Component Description : | Mopar All-Weather Floor Mat Kit | |
| Component Part Number : | 82215322AB | |
| Component Name : | Mopar All-Weather Floor Mat Kit | |
| Component Description : | Mopar All-Weather Floor Mat Kit | |
| Component Part Number : | 82215322AC | |
| Component Name : | Mopar All-Weather Floor Mat Kit | |
| Component Description : | Mopar All-Weather Floor Mat Kit | |
| Component Part Number : | 82215323AB | |

20E-060

| * | Mopar All-Weather Floor Mat Kit |
|---------------------------|---------------------------------|
| | Mopar All-Weather Floor Mat Kit |
| Component Part Number : | 82215323AC |
| | |
| Component Name : | Mopar All-Weather Floor Mat Kit |
| Component Description : | Mopar All-Weather Floor Mat Kit |
| Component Part Number : | 82215421AB |
| | |
| - | Mopar All-Weather Floor Mat Kit |
| Component Description : | Mopar All-Weather Floor Mat Kit |
| Component Part Number : | 82215421AC |
| Comment News | |
| - | Mopar All-Weather Floor Mat Kit |
| | Mopar All-Weather Floor Mat Kit |
| Component Part Number : | 82215422AB |
| Component Name : | Mopar All-Weather Floor Mat Kit |
| Component Description : | Mopar All-Weather Floor Mat Kit |
| Component Part Number : | 82215422AC |
| | |
| | |
| Supplier Identification : | |
| Component Manufacturer | |
| Name : NR | |
| Address : NR | |
| NR Country : NR | |
| Sound J. Mit | |
| | |

Chronology :

• On December 18, 2019, the FCA US LLC ("FCA US") Vehicle Safety and Regulatory Compliance ("VSRC")

organization opened an investigation as a result of a field report claiming an accelerator pedal stuck on an allweather floor mat on a 2019 Ram 1500 vehicle.

• From December 2019, through February 2020, FCA US VSRC and FCA US Engineering coordinated several dealership visits to inspect vehicles exhibiting the interference condition. Pedal assemblies and floor mats from these vehicles were returned for lab analysis, and one vehicle was bought back to further support analysis. A floor mat clearance study was also performed to measure floor mat clearance measurements across numerous FCA US vehicles.

• From February 2020, through July 2020, FCA US Engineering conducted dimensional analysis studies on pedal assemblies and floor mats from the field and conducted scans of the parts and vehicles to determine whether, and under what circumstances, interference between the pedal assembly and the all-weather floor mat might occur.

• As of August 20, 2020, FCA US has identified zero CAIRs, zero warranty claims, and zero field reports potentially relating to these Mopar all-weather floor mat kits.

• As of August 20, 2020, FCA US is not aware of any accidents or injuries potentially relating to these Mopar allweather floor mat kits.

• On August 20, 2020, FCA US determined, through the Vehicle Regulations Committee, to conduct a voluntary safety recall of the affected units.

Description of Remedy :

| Description of Remedy Program : | FCA US will conduct a voluntary safety recall to remove some material from the raised features of the driver floor mats to mitigate the potential for interference with the accelerator pedal on all affected floor mats. |
|---|---|
| | FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense. |
| | The remedy component will be a driver all-weather floor mat with the raised ribs removed from the accelerator pedal area. |
| Identify How/When Recall Condition was Corrected in Production : | NR |

20E-060

Recall Schedule :

| Description of Recall Schedule : | **08/27/2020: FCA US will notify dealers and begin notifying owners on |
|------------------------------------|--|
| | or about 10/16/2020. |
| Planned Dealer Notification Date : | OCT 16, 2020 - OCT 16, 2020 |
| Planned Owner Notification Date : | OCT 16, 2020 - OCT 16, 2020 |

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR Address : NR NR Country : NR Company Phone : NR

* NR - Not Reported